

# Machine Hazard Notice

## ANGLEBRACE REBATER SAWS

### ATTENTION: OWNERS OF ANGLEBRACE REBATER SAWS

Owners of Anglebrace Rebater Saws, manufactured by Mitek Australia Ltd, are advised to read the attached notice carefully. It contains important information concerning the control of a hazard associated with the use of the Anglebrace Rebater Saw.

Makita Australia is undertaking a voluntary recall of the circular saw model 5806B for modification of the guard assembly. This saw forms the basis of the Anglebrace Rebater sold by Mitek Australia. Mitek recommends that owners of Anglebrace rebaters follow the recall notice below.



## PRODUCT SAFETY RECALL



**Circular Saw models  
5606B, 5806B, 5740NB**

In the interest of end user safety Makita Australia is undertaking a voluntary recall of circular saw models **5606B, 5806B, 5740NB** for modification of the saw blade guard assembly.

Recall applies to all stock manufactured (since 1996) and therefore applies to all serial numbers of the above models.

**Condition:**  
On these models only, it is possible that the inner saw blade guard can be improperly jammed in the fully retracted position, and subsequently expose the user to the rotating blade.

**Rectification:**  
The affected models require replacement of a rubber sleeve within the guard assembly. This modification will be carried out by Makita's national service agent network.

**Action Required:**  
Owners should cease using these models immediately and contact Makita Australia on **1300 361 690** between 8:00am and 6:00pm E.S.T. to arrange modification by the nearest Makita Service Agent at no charge.

Makita (Aust) Pty Ltd 92 Wetherill St, Silverwater NSW 2128	Private Bag 160, Silverwater NSW 1811 Fax: 1300 361 770	circularsawrecall@makita.com.au www.makita.com.au
---	---	--

**See [www.recalls.gov.au](http://www.recalls.gov.au) for Australian product recall information**

### IMMEDIATE ACTION REQUIRED

Owners of Anglebrace Rebater Saws should implement the above-mentioned control procedures immediately.

Queries regarding this Hazard Notice should be directed to the Machinery Support Engineer at Mitek Australia Ltd on Ph: (03) 8795 8888.