

### New Hazard ID & Risk Assessment Information

Owners of 'Stud Noggin Nailer' Machines manufactured by Stanley Bostitch (The Stanley Works P/L) are advised to read this document carefully. It contains important information concerning the control of hazards associated with this machine.

#### HAZARD DESCRIPTION


A hazard analysis & risk assessment and has been conducted by MiTek Australia Ltd on a recent version of the Stanley Bostitch Stud Noggin Nailer machine. Customers operating this machine are advised that a new state of knowledge exists regarding the hazards associated with the operation of the Stud Noggin Nailer.



***WARNING: Operators risk serious injuries from the hazards identified in this assessment. Plant managers are advised to take immediate action to ensure that all hazards are adequately controlled.***

#### HAZARD CONTROL MEASURES

Mitek urges customers with a Bostitch Stud Noggin Nailer to review their own hazard control measures for this machine whilst considering all relevant recommendations arising from the Mitek risk assessment and hazard analysis for this machine.



Queries regarding this Hazard Notice should be directed to the Machinery Support Engineer at MiTek Australia Ltd on Ph: 03 8795 8888. Written on 20-11-2006.