Exova Warringtonfire Aus Pty Ltd Suite 2002a, Level 20 44 Market Street Sydney, New South Wales 2000 Australia

Postal Address: Suite 2002a, Level 20 44 Market Street Sydney, New South Wales 2000

Australia

T: +61 (0)2 8270 7600 F: +61 (0)2 9299 6076 W: www.exova.com



Testing. Advising. Assuring.

EWFA CERTIFICATE OF ASSESSMENT	CERTIFICATE No : SFC 37600400B.2 Page 1	. ∩f 1
LWIA CLITIIICATE OF ASSESSIMENT	CEITHICATE NO. SIC 3/000700D.2 FAUCT	

Report Sponsor	Certificate Issue Date	Product Name
Forest and Wood Products Australia Level 11, 10-16 Queen Street, Melbourne VIC 3000, Australia	20/05/2016	Mitek Posi-strut metal strut web beams

Referenced Assessment Report	Referenced Standards	Report Issue Date	Report Validity Date
EWFA 37600400B.2	AS1530.4-2014	20/05/2016	28/02/2021

Introduction

The element of construction described below was assessed by this laboratory on behalf of the report sponsor in accordance with the stated test standard and achieved the results stated below. Refer to the referenced assessment report(s) or Regulatory Information Report(s) for a complete description of the assessed construction.

Description of Assessed Product and Performance	Assessed FRL
The scope of the assessment includes the fire resistance level (FRL) of timber-framed floor/ceiling systems incorporating Mitek Posi-strut metal strut web beams when tested in accordance with AS1530.4-2014.	FRL: 90/90/90 RISF > 60 minutes
Refer to the referenced assessment report(s) or Regulatory Information Report(s) for a complete description of the assessed construction.	

Conditions/Validity

- THIS CERTIFICATE IS PROVIDED FOR GENERAL INFORMATION ONLY AND DOES NOT COMPLY WITH THE REGULATORY REQUIREMENTS FOR EVIDENCE OF COMPLIANCE.
- Reference should be made to the relevant assessment report(s) or Regulatory Information Report to determine the applicability of the test result to a proposed installation. Full details of the constructions and justification for the conclusions given, along with the validity statements, are given in the assessment report(s) or Regulatory Information Report(s).
- The results of these fire tests may be used to assess fire hazard, but it should be recognized that a single test method will not provide a full assessment of fire hazard under all conditions.

TESTING AUTHORITY	Exova Warringtonfire Aus Pty Ltd		
Address	Suite 2002a, Level 20, 44 Market Street, Sydney NSW 2000, Australia		
Phone / Fax	+61 (0)2 8270 7600 / +61 (0)2 9299 6076		
ABN	81 050 241 524		
Email / Home Page	www.exova.com		
Authorisation	Prepared By:	Reviewed By:	
	fr Mh.	Jula South	
	S. Hu	K. Nicholls	

